

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General							
Zone		Ward No.		Ward Name			
YELAHANKA		11		Kuvempu Nagar			
Street ID		Street Name		Significant Landmark			
W0723, W0745, I0721, W0660, W0743, W0741		NA, 2nd Main Rd, 3rd Main Rd		Doddachannappa layout Raghuram layout			
Segment No.		Total Length (m)					
11/C-W0723/S081508		234.77					
Segment Details							
Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	100.24	77.548056	13.057619	77.548111	13.058523	I0246	W0660
2	75.18	77.549102	13.060456	77.549048	13.059778	W0723	SWD
3	59.35	77.549299	13.060421	77.549255	13.059886	W0723	SWD
Work Details							
History of Road / Lane / Circles							
Name of the Work		Sanctioned Estimated Amount (Rs.)			Sanctioned Year		
Improvements to Road and Drains at Devappa layout Mariyamma block Doddachannappa layout Raghuram layout in ward no 11 (Kuvempunagara) Vidyanarayapura		4900000			2015		
Year		Type of Work			Other Work Type		
2015 - 2016		Asphalting					
Tender		Work Details			Job No. / Work Code		
Tender		Improvements to Road and Drains at Devappa layout Mariyamma block Doddachannappa layout Raghuram layout in ward no 11 (Kuvempunagara) Vidyanarayapura Sub-Division Yelahanka zone			011-16-000009		
Work Order No.		Work Order Date			Period of Extention		
EE/BTP/BBMP/E-PMT/WO/192/2015-16		03/02/2016			90 DAYS		
Defect Liability Period From		Defect Liability Period To			Multiple road involved with the same Job No/ Work Code #		
03/02/2016		02/02/2017			Yes		
Contractor Details							
Name of Contractor		Contractor Reg No (BBMP/PWD)			Expenditure Booked \ Released (Rs)		
Zone: YELAHANKA		Ward No: 11			Ward Name: Kuvempu Nagar		
					Street ID: W0723, W0745, I0721, W0660, W0743, W0741		

Phone No.

E-Mail ID

8553121546

Field Inspection Details

Number of Trees

Any Other Information

Name

3

SURESH

Date of Inspection

Remarks

21/09/2016

COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks				
Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAI AH	21/09/2016	21/10/2016	COMPLETED
SE	VASU K M	21/09/2016	21/10/2016	COMPLETED
EE	YARAPPA REDDY	21/09/2016	21/10/2016	COMPLETED
AEE	SHIVAKUMAR	21/09/2016	21/10/2016	COMPLETED
AE	SURESH	21/09/2016	21/10/2016	COMPLETED
AE	SURESH	21/09/2016	21/10/2016	COMPLETED